Project No. 805/69
File Code No. 3,6, 9.35

Doc No.

URS

LETTER OF TRANSMITTAL

TO: Paul Peronard - US EPA

FROM: Jim Stout - URS

DATE: September 22, 2000

PROJECT TITLE: Export Plant Removal Action - Libby, MT - Weekly Progress Report

WE ARE SENDING YOU THE FOLLOWING ATTACHMENTS:

ITEM NO.	FILE CODE	DESCRIPTION	DATE	COPIES
1	6.2.b.1.8	Weekly Progress Report for two weeks of September 08 through September 21, 2000	9/22/00	3
2	4.5.b.4.78	TEM sample results for the highest counts collected on each of six days (August 22,23,24,25,28,and 29, 2000) and analyzed by R.J. Lee Group, Inc.	9/22/00	1
3	4.5.b.2.55-57	Personal Air Sample Results for 9/12/00	9/12/00	1
4	4.5.b.4.55-56	Inside/Outside Work Area Air Sample results for 9/12/00	9/12/00	1
5	4.5.b.4.57-58	Perimeter Air Sample Results for 9/13/00	9/13/00	1
6	4.5.b.4.59-60	Mine Glory Hole Work Area and Personal Air Sample Results for 9/14/00	9/14/00	1
7	4.5.b.2.58-60	Personal and Excursion Air Sample Results for 9/15/00	9/15/00	1
8	4.5.b.4.61-62	Perimeter Air Sample Results for 9/15/00	9/15/00	1
9	4.5.b.4.63-65	Mine Glory Hole Work Area and Personal Air Sample Results for 9/15/00	9/15/00	1
10	4.5.b.2.61-63	Personal and Excursion Air Sample Results for 9/16/00	9/16/00	1
11	4.5.b.4.66-67	Perimeter Air Sample Results for 9/16/00	9/16/00	1
12	4.5.b.2,64-66	Personal and Excursion Air Sample Results for 9/17/00	9/17/00	1
13	4.5.b.4.68-71	Inside/Outside Work Area and Perimeter Air Sample Results for 9/17/00	9/17/00	1
14	4.5.b.2.67-69	Personal and Excursion Air Sample Results for 9/18/00	9/18/00	1
15	4.5.b.4.72 - 75	Inside/Outside Work Area and Perimeter Air Sample Results for 9/18/00	9/18/00	1
16	4.5.b.2.70-72	Personal and Excursion Air Sample Results for 9/19/00	9/19/00	1
17	4.5.b.4.76-77	Outside Work Area and Perimeter Air Sample Results for 9/19/00	9/19/00	1
18	4.5.b.2.73-75	Personal and Excursion Air Sample Results for 9/20/00	9/20/00	1
19	4.5.b.4.79-80	Outside Work Area and Perimeter Air Sample Results for 9/20/00	9/20/00	1
20	4.5.b.2.76-78	Personal and Excursion Air Sample Results for 9/21/00	9/21/00	1
21	4.5.b.4.81-82	Outside Work Area and Perimeter Air Sample Results for 9/21/00	9/21/00	1
22	4.5.b.4.83-85	Mine Glory Hole Work Area and Personal Air Sample Results for 9/121/00	9/21/00	1